

FIG. 1





FIG. 2



IN THE CASE WHERE THERE ARE FOUR JOURNAL
BEARING PORTIONS IN CYLINDER BLOCK IN V6 ENGINE

FIG. 3




FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 6




FIG. 7




FIG. 8

